



# Wheel Warranty Conditions



<b>COVERED</b> Warranty Conditions	<b>NOT COVERED</b> Warranty Conditions
<p><b>PAINT (1-Year):</b></p> <ul style="list-style-type: none"> <li>• Corrosion</li> <li>• Clear Coat Peeling</li> <li>• Chrome/Galvanized Corrosion</li> </ul> <p><b>CONSTRUCTION:</b></p> <ul style="list-style-type: none"> <li>• Pinhole Leak</li> <li>• Nonconforming Weld</li> </ul> <p><b>OTHER:</b></p> <ul style="list-style-type: none"> <li>• Aluminum Lifetime Structural Warranty <ul style="list-style-type: none"> <li>○ Under intended use</li> </ul> </li> <li>• Steel 1-Year Structural Warranty <ul style="list-style-type: none"> <li>○ Under intended use</li> </ul> </li> </ul>	<p><b>ROAD HAZARDS:</b></p> <ul style="list-style-type: none"> <li>• Curbing</li> <li>• Bent</li> <li>• Impact Damage</li> <li>• Tire Ran Underinflated to Destruction</li> </ul> <p><b>DAMAGE:</b></p> <ul style="list-style-type: none"> <li>• Improper Repair</li> <li>• Modification</li> <li>• Mounting Damage</li> <li>• Chemical Contamination</li> <li>• Fire Damage</li> <li>• Vandalism</li> </ul> <p><b>OTHER:</b></p> <ul style="list-style-type: none"> <li>• Cannot Balance</li> <li>• Over 1-year for appearance</li> <li>• Over 1-year for steel structural</li> <li>• Unit Damages (Fender, Structure, Cargo, etc.)</li> </ul>






**IMPORTANT:** The adjustment process does not involve the kind of analysis necessary to determine the existence of a covered warranty condition. The conditions shown are for illustration only and should not be considered as proof of workmanship or material condition. A wheel may be adjusted for a condition that may have resulted from one of many possible causes. Neither the presence of a condition nor the fact that a wheel is adjusted for a condition establishes that a problem exists in the wheel.



# Wheel Warranty Conditions



**COVERED**



**IMPORTANT:** The adjustment process does not involve the kind of analysis necessary to determine the existence of a covered warranty condition. The conditions shown are for illustration only and should not be considered as proof of workmanship or material condition. A wheel may be adjusted for a condition that may have resulted from one of many possible causes. Neither the presence of a condition nor the fact that a wheel is adjusted for a condition establishes that a problem exists in the wheel.

Rev 03/19



# Wheel Warranty Conditions



## NOT COVERED



**Curbing**



**Bent**



**Impact Damage**



**Ran Underinflated to Destruction**



**Improper Repair**



**Modification**



**Chemical Contamination**



**Fire Damage**



**Vandalism**

**IMPORTANT:** The adjustment process does not involve the kind of analysis necessary to determine the existence of a covered warranty condition. The conditions shown are for illustration only and should not be considered as proof of workmanship or material condition. A wheel may be adjusted for a condition that may have resulted from one of many possible causes. Neither the presence of a condition nor the fact that a wheel is adjusted for a condition establishes that a problem exists in the wheel.  
Rev 03/19